



PALM BEACH AIRCRAFT PROPELLER, INC.

2633 Lantana Road, Suite 23 Building 1501
Lantana Airport Lantana Florida 33462
800-965-7767 561-965-7767 561-965-7933(FAX)
F.A.A. Approved Repair Station No. LU4R349M
EASA Acceptance Certificate #145.5271
E-mail: info@pbapi.com

Sept, 29, 2020

Dear Valued Customers, FBO's and Concerned Authorities;

This letter is to inform you that governors overhauled by Palm Beach Aircraft Propeller Inc. are not affected by Service Bulletin ASB273C and A.D. 2020-19-06 because we never installed a BA-59 bearing in an overhauled governor that the factory is having a problem with.

Please include this notification as a permanent record.

Should you have any questions or need further information, feel free to contact me

Sincerely,

Larry Harris

VP/GM/MC

Palm Beach Aircraft Propeller Inc.

FAA# LU4R349M -- EASA# 145.5271

Sales and Service, for Props, Governors, NDT, Plating

AeroScan M5 Blade Measuring, Owner-User

PH. 1-800-965-7767

PH.1-561-965-7767

FAX 561-965-7933